



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Country Club Hills			System ID Number:		IL0310540		Current Inventory Date:		2024			
*Please enter totals in the empty box next to each category	Total Service lines:	5781	Total Lead:	0	Total Non-Lead:	5781	Total Galvanized Requiring replacement:	0	Total Unknown:	0	Website link to Material Inventory:		countryclubhills.org		

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". / If address is not a lead and copper sample site mark "N/A"	<b>EXAMPLES:</b>  Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities  Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? <b>EXAMPLES:</b> Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	<b>EXAMPLES:</b> Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (LNL)	<b>EXAMPLES:</b> Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (LNL)	<b>EXAMPLES:</b> Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (LNL)	<b>EXAMPLES:</b> Lead (L) Galvanized Requiring Replacemnt (GRR) Non-Lead (NL) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (LNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	<b>EXAMPLES:</b> Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
18721 CASTLE DARGAN DR	N/A	N	N	2005	2005	Maintenance Records	C	C	C	NL	N	N/R	N		N		
4027 W 183 ST	N/A	N	N	UNKNOWN	UNKNOWN	Visual during meter replacement	C	C	C	NL	N	N/R	N		N		
18348 PULASKI	N/A	N	N	1954	1954	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
4023 W 183 ST	N/A	Y	N	UNKNOWN	UNKNOWN	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
18350 PULASKI	N/A	N	N	1954	1954	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
19320 CHESTNUT	N/A	Y	N	UNKNOWN	UNKNOWN	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
4931 WILSHIRE	N/A	N	N	1970-1992	1970-1992	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
4001 FLOSSMOOR	N/A	N	N	1986	1986	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
4051 FLOSSMOOR	N/A	N	N	1983	1983	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
4051A FLOSSMOOR	N/A	N	N	1983	1983	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
4101 FLOSSMOOR	N/A	N	N	2005	2005	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
4050 FLOSSMOOR	N/A	N	N	1985 - 1990	1985 - 1990	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		
18660 CICERO	N/A	N	N	1997	1997	Maintenance Inspections	C	C	C	NL	N	N/R	N		N		